

Date	Version	Description
----	-----	-----
10/26/00	1.7.3	Initial Release
11/15/00	1.7.4	Updated Module Configuration Form * Added Configuration Strap bits to RIM * Fixed PCU configuration "lock/unlock" download * Add Serial Number to RIM
01/29/02	2.0.3	Fixed Resizing on all Forms Recompile with new library for better operation on XP Added Blood form for use with PLC/TCU
04/15/02	2.1.3	Added ".bld" support to Blood form forDFS user Fixed PCU configuration not working Added T200 radio program configuration Add comm port configuration to Blood
03/19/02	2.3.1	Added TCU module configuration panels Added Hardware REV to Patch form Fixed PCU form Alarm Horn Override & Alarm Light Disable Fixed Module Configure form - PLC block read Updated help for above
03/31/03	2.4.5	Fixed setting pulse points on module type set.

		Fixed Network UDP Tunnel and RTU functions
		Fixed Help Install
01/18/04	2.5.2	Fixed setting pulse points on module type set.
		Fixed Network UDP Tunnel and RTU functions
		Add Modbus mode select to RIM configuration
		Added TCU Audialer support to Module Configuration form.
		Added new radio T200 programming algorithm to program 218-220 Mhz
10/31/05	2.6.0	Added support for up to 10 serial ports with new Config-Comm form
		Removed RTS-KEY(radio) function
		Fixed Config-Auto when polling TCU
12/08/05	2.7	Added TCU Phase Monitor Calibration to TCU pannel in module config
		Added RIM cfg files for Max Radio Threshold
01/27/05	2.7.2	Fixed TAC2Sim, Win98 install, Comm setup lables
	2.7.3	Added Modbus RTU and parity to RIM configuration pannel
01/30/07	2.7.4	Added Single Phase Option and Phase Monitor Multiplier Adjust Box to TCU Panel
06/14/07	2.7.5	Added support for T200B radio frequency programming
	2.7.6	Fixed NIM RTU polling over internet
	2.7.7	Fixed crash when comm port not available on "unpause"
	2.7.8	Fixed crash when computer has large number of comm ports available
	2.8.0	Added support for "Table Data" messages
		Set parity/bits to 7n2e when comm port opened

	2.9.0	Update T200 Radio programming for TIM007
	2.9.3	Updated "Program Update"
	2.9.6	Remove Linux Basic output from Blood
10/24/11	2.10.1	Added Bubbler/HiOverride to TCU configuration
01/16/12	2.10.2	Fixed Modbus baud setting crash. Changed Helpfile 't-o-c' to 'index'
05/23/12	2.11.0	Update for Windows 7
07/26/12	2.11.1	Fixed patch to non TIM modules
09/04/12	2.11.5	Fixed Modbus Configuration in TCU9000 form
06/03/14	2.12.3	Add patching support for TCUB. Add auto-scroll to PLC memory form. Change documents and ini path to \Users\Public\DFS\WinRTUTest
11/01/16	2.13.8	Add VDR and XT200 radio programming feature.
11/30/21	2.15.12	Add TCU800 radio profile interface
03/15/22	2.15.13	Fixed error writing the configuration to the TCU using the TCU90000 module config form